
# Reserve Study Update Ridgewood Trails Community Development District Clay County, Florida



Prepared for FY 2021 Report Date: January 15, 2021





January 15, 2021

Mr. Ernesto Torres, District Manager Governmental Management Services 475 West Town Place, Suite 114 St. Augustine Florida 32092

Re: Reserve Study Report for Ridgewood Trails Community Development District

Dear Mr. Torres:

Community Advisors is pleased to provide this Reserve Study report for the above referenced District. A site visit was conducted to determine the condition of your major components and provide an opinion of their remaining useful life.

We have developed a plan to fund future capital component replacements which is dependent on adequate funding, component maintenance, usage, weather and other factors. Component replacement cost is determined using local vendors and industry standard publications. This Reserve Study was prepared under the guidelines of the National Reserve Study Standards which is administrated by CAI and the Standards of Practice establish by APRA. Once you have reviewed this report and considered recent expenditures and any historic cost data, we will make necessary adjustments

Respectively submitted,

CRShamand

Charles R. Sheppard RS PRA CCI

Professional Reserve Analyst

10459 Hunters Creek Court Jacksonville, FL 32256 (904) 303-3275

www.communityadvisors.comm









#### **TABLE OF CONTENTS**

EXECUTIVE SUMMARY	
Executive Summary	1-1
Current Funding Projection	1-2
Current Funding Projection vs Fully Funded Plan	1-3
FUNDING PLAN	
Threshold Funded Plan	2-1
Recommended Funding Plan Chart	2-2
CASH FLOW	
Income & Expense Spreadsheet	3-1
EXPENDITURE DETAIL	
Annual Expenditure Detail	4-1
Asset Current Cost by Category	4-9
COMPONENT INVENTORY	
Component Inventory	5-1
Component Detail Index	5-3
Component Detail	5-5
DISCLOSURERS & INFORMATION	
Methodology & Information	6-1
Terms of Service	6-2
Definitions	<i>c</i> 2

#### **Ridgewood Trails Community Development District**

Clay County, Florida **Executive Summary** 

Report Date January 15, 2021

Budget Year Beginning October 1, 2021 Budget Year Ending September 30, 2022 Report Parameters

Inflation 2.50%
Annual Assessment Increase 1.50%
Interest Pate on Passarya Denocit 1.00%

Interest Rate on Reserve Deposit 1.00%

2021 Beginning Balance \$164,500

#### **GENERAL INFORMATION**

Date of Completion: January 1, 2017
 Date of site visit: December 16, 2020

• Components Included: 40

• Current replacement cost: \$476,292

• Level of Service: Level II Update

• Funding Method: The Cash Flow Method

• Funding Goal: Adequate funding with moderate contributions

#### FINANCIAL INFORMATION

Fully Funded Reserve Balance: \$171,341Current Funding Plan %: 96%

• Full Funding Surplus/Deficit: Deficit of \$6,841

Full Funding Contribution: \$25,774
Total Full Funding Contribution: \$32,615
Current Contribution: \$35,000

Current Plan Performance: Adequate for future component funding

• Recommend Contribution: \$35,757 provides adequate funding slightly higher funding level


#### Threshold Funding Model Summary of Calculations

Required Annual Contribution \$35,757.40
Average Net Annual Interest Earned \$1,897.65
Total Annual Allocation to Reserves \$37,655.05

#### Ridgewood Trails Community Development District Current Funding Projection

Beginning Balance: \$164,500

υ		,			Projected	Fully	
	Current	Annual	Annual	Annual	Ending	Funded	Percent
Year	Cost	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
21-22	476,292	35,000	1,890	10,493	190,897	195,066	98%
22-23	488,200	35,525	2,223	4,100	224,546	226,693	99%
23-24	500,405	36,058	2,522	8,405	254,721	255,779	100%
24-25	512,915	36,599	2,881	3,231	290,970	291,696	100%
25-26	525,738	37,148	2,987	29,465	301,639	302,442	100%
26-27	538,881	37,705	3,358	3,584	339,117	340,826	99%
27-28	552,353	38,271	3,693	8,118	372,962	376,385	99%
28-29	566,162	38,845	2,963	115,493	299,277	303,658	99%
29-30	580,316	39,427	2,611	77,652	263,663	268,805	98%
30-31	594,824	40,019	2,999	3,747	302,935	309,763	98%
31-32	609,695	40,619	3,436		346,989	356,537	97%
32-33	624,937	41,228	3,336	54,583	336,971	349,509	96%
33-34	640,560	41,847	3,010	77,834	303,993	319,472	95%
34-35	656,574	42,474	3,421	4,367	345,521	365,013	95%
35-36	672,989	43,111	3,886		392,519	417,220	94%
36-37	689,813	43,758	4,319	4,345	436,251	467,356	93%
37-38	707,059	44,414	4,063	74,329	410,400	448,115	92%
38-39	724,735	45,081	3,740	81,528	377,692	422,146	89%
39-40	742,854	45,757	4,188	4,679	422,957	475,457	89%
40-41	761,425	46,443	4,694		474,095	536,087	88%
41-42	780,461	47,140	4,252	96,017	429,470	501,034	86%
42-43	799,972	47,847	4,298	47,552	434,062	516,029	84%
43-44	819,971	48,565	2,394	243,224	241,798	332,116	73%
44-45	840,471	49,293	2,911		294,002	394,222	75%
45-46	861,482	50,033	3,251	18,978	328,307	439,773	75%
46-47	883,019	50,783	3,791		382,881	507,295	75%
47-48	905,095	51,545	2,198	214,611	222,012	357,940	62%
48-49	927,722	52,318	2,435	30,853	245,912	394,653	62%
49-50	950,915	53,103	2,457	53,294	248,178	410,766	60%
50-51	974,688	53,899	2,956	6,483	298,550	476,785	63%




This chart illustrates the current funding plan performance.

#### Ridgewood Trails Community Development District Threshold Funded Plan

Beginning Balance: \$164,500

υ		,			Projected	Fully	
	Current	Annual	Annual	Annual	Ending	Funded	Percent
Year	Cost	Contribution	Interest	Expenditures	Reserves	Reserves	Funded
21-22	476,292	35,757	1,898	10,493	191,662	195,066	98%
22-23	488,200	36,294	2,239	4,100	226,095	226,693	100%
23-24	500,405	36,838	2,545	8,405	257,073	255,779	101%
24-25	512,915	37,391	2,912	3,231	294,146	291,696	101%
25-26	525,738	37,952	3,026	29,465	305,659	302,442	101%
26-27	538,881	38,521	3,406	3,584	344,001	340,826	101%
27-28	552,353	39,099	3,750	8,118	378,732	376,385	101%
28-29	566,162	39,685	3,029	115,493	305,953	303,658	101%
29-30	580,316	40,280	2,686	77,652	271,268	268,805	101%
30-31	594,824	40,885	3,084	3,747	311,490	309,763	101%
31-32	609,695	41,498	3,530		356,518	356,537	100%
32-33	624,937	42,120	3,441	54,583	347,496	349,509	99%
33-34	640,560	42,752	3,124	77,834	315,538	319,472	99%
34-35	656,574	43,393	3,546	4,367	358,110	365,013	98%
35-36	672,989	44,044	4,022		406,176	417,220	97%
36-37	689,813	44,705	4,465	4,345	451,001	467,356	97%
37-38	707,059	45,376	4,220	74,329	426,268	448,115	95%
38-39	724,735	46,056	3,908	81,528	394,704	422,146	93%
39-40	742,854	46,747	4,368	4,679	441,140	475,457	93%
40-41	761,425	47,448	4,886		493,474	536,087	92%
41-42	780,461	48,160	4,456	96,017	450,073	501,034	90%
42-43	799,972	48,882	4,514	47,552	455,917	516,029	88%
43-44	819,971	49,616	2,623	243,224	264,933	332,116	80%
44-45	840,471	51,588	3,165		319,686	394,222	81%
45-46	861,482	52,362	3,531	18,978	356,601	439,773	81%
46-47	883,019	53,148	4,097		413,846	507,295	82%
47-48	905,095	53,945	2,532	214,611	255,711	357,940	71%
48-49	927,722	54,754	2,796	30,853	282,408	394,653	72%
49-50	950,915	55,575	2,847	53,294	287,536	410,766	70%
50-51	974,688	56,409	3,375	6,483	340,837	476,785	71%



This chart shows the threshold plan contributions with annual expenditures.

	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31
Beginning Balance Annual Assessment Interest Earned	164,500 35,757 1,898	191,662 36,294 2,239	226,095 36,838 2,545	257,073 37,391 2,912	294,146 37,952 3,026	305,659 38,521 3,406	344,001 39,099 3,750	378,732 39,685 3,029	305,953 40,280 2,686	271,268 40,885 3,084
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	10,493 195,066 98% 191,662	4,100 226,693 100% 226,095	8,405 255,779 101% 257,073	3,231 291,696 101% 294,146	29,465 302,442 101% 305,659	3,584 340,826 101% 344,001	8,118 376,385 101% 378,732	115,493 303,658 101% 305,953	77,652 268,805 101% 271,268	3,747 309,763 101% 311,490
<b>Description</b> Misc. Site Components Asphalt Mill & Overlay - Parking Lot										
Landscape & Irrigation Allowance Light Pole - Parking Lot			5,253					5,943		
Monument Sign Refurbishment Allowance Misc. Site Components Total:			3,152 <b>8,405</b>					5,943		
Storm Water System			3,102					,		
Storm Water System Total:								17,830 <b>17,830</b>		
Fencing & Gates Aluminum Fencing - Cabana Aluminum Fencing - Clubhouse Aluminum Fencing - Playground Fencing & Gates Total:										
Misc. Building Components Cabinets/Tops - Clubhouse Addition Restroom Renovation - Cabana										
Restroom Renovation - Clubhouse Water Coolers - Clubhouse Window & Door Allowance								16,642 2,330		
Misc. Building Components Total:								18,971		

	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31
Description	41-44	44-4J	4J-4 <b>4</b>	<b>47-4</b> 3	<i>43-4</i> 0	20-27	21-20	20-27	47-30	30-31
Roofing										
Asphalt Shingles - Cabana										
Asphalt Shingles - Clubhouse										
Asphalt Shingles - Clubhouse Addition										
Roofing Total:										
Painting										
Exterior Painting - Cabana					2,601					
Exterior Painting - Clubhouse	5,709								6,956	
Exterior Painting - Clubhouse Addition					2 (01	3,584			( 05(	
Painting Total:	5,709				2,601	3,584			6,956	
Flooring										
Carpet - Fitness	1,784								2,173	
Flooring Allowance - Clubhouse Addition										
Flooring Total:	1,784								2,173	
Furniture Fixtures & Equipment										
Access Control/Camera Allowance								4,755		
Fitness Equipment Allowance		4,100					4,639			
Pool Furniture Allowance	3,000	4.400		3,231			3,479			3,747
Furniture Fixtures & Equipment Total:	3,000	4,100		3,231			8,118	4,755		3,747
HVAC										
Heat Pump - Clubhouse Addition										
Heat Pump- Fitness					7,064					
HVAC Total:					7,064					
Swimming Pool - Phase I										
Concrete Pavers - Pool Deck										
Filtration Refurbishment Allowance										
Pool Lift					10.000			6,657		
Pool Resurfacing/Tile Swimming Pool - Phase I Total:					19,800 <b>19,800</b>			6 657		
Swimming Pool - Phase I Total:					19,800			6,657		

	21-22	22-23	23-24	24-25	25-26	26-27	27-28	28-29	29-30	30-31
Description										
Swimming Pool - Phase II										
Concrete Pavers - Pool Deck										
Filtration Refurbishment Allowance										
Pool Lift										
Pool Resurfacing									68,523	
Pool Slide & Tower Refurbishment Allowance										
Wood Pergola										
Swimming Pool - Phase II Total:									68,523	
Playground										
Plastic Mulch Border										
Play Equipment Allowance								53,491		
Site Furnishing Allowance								3,566		
Swings - Tripod 2 Bay								4,279		
Playground Total:								61,336		
Components Not Included										
Electrical Panels/Wiring	Unfunded									
Fire Detection System	Unfunded									
Message Board	Unfunded									
Pool Furniture Full Replacement	Unfunded									
Pool Pumps/Equip Partial Replacement	Unfunded									
Site Utilities	Unfunded									
Water Coolers - Cabana	Unfunded									
Year Total:	10,493	4,100	8,405	3,231	29,465	3,584	8,118	115,493	77,652	3,747

	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41
Beginning Balance Annual Assessment Interest Earned	311,490 41,498 3,530	356,518 42,120 3,441	347,496 42,752 3,124	315,538 43,393 3,546	358,110 44,044 4,022	406,176 44,705 4,465	451,001 45,376 4,220	426,268 46,056 3,908	394,704 46,747 4,368	441,140 47,448 4,886
Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance	356,537 100% 356,518	54,583 349,509 99% 347,496	77,834 319,472 99% 315,538	4,367 365,013 98% 358,110	417,220 97% 406,176	4,345 467,356 97% 451,001	74,329 448,115 95% 426,268	81,528 422,146 93% 394,704	4,679 475,457 93% 441,140	536,087 92% 493,474
Description Misc. Site Components			•• 400							
Asphalt Mill & Overlay - Parking Lot Landscape & Irrigation Allowance Light Pole - Parking Lot Monument Sign Refurbishment Allowance			25,488 6,724 4,035					7,608 10,043		
Misc. Site Components Total:			36,247					17,651		
Storm Water System Stormwater Pond Allowance Storm Water System Total:										
Fencing & Gates Aluminum Fencing - Cabana										
Aluminum Fencing - Clubhouse Aluminum Fencing - Playground Fencing & Gates Total:								11,613 13,037 <b>24,650</b>		
Misc. Building Components Cabinets/Tops - Clubhouse Addition								4,565		
Restroom Renovation - Cabana Restroom Renovation - Clubhouse Water Coolers - Clubhouse		15,745								
Window & Door Allowance Misc. Building Components Total:		15,745						13,695 <b>18,259</b>		

	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41
Description										
Roofing										
Asphalt Shingles - Cabana							7,912			
Asphalt Shingles - Clubhouse			17,094							
Asphalt Shingles - Clubhouse Addition								11,230		
Roofing Total:			17,094				7,912	11,230		
Painting										
Exterior Painting - Cabana			3,169							
Exterior Painting - Clubhouse							8,475			
Exterior Painting - Clubhouse Addition				4,367						
Painting Total:			3,169	4,367			8,475			
Flooring										
Carpet - Fitness							2,648			
Flooring Allowance - Clubhouse Addition			10,544							
Flooring Total:			10,544				2,648			
Furniture Fixtures & Equipment										
Access Control/Camera Allowance										
Fitness Equipment Allowance		5,248					5,938			
Pool Furniture Allowance			4,035			4,345			4,679	
Furniture Fixtures & Equipment Total:		5,248	4,035			4,345	5,938		4,679	
HVAC										
Heat Pump - Clubhouse Addition								9,738		
Heat Pump- Fitness							9,501			
HVAC Total:							9,501	9,738		
Swimming Pool - Phase I										
Concrete Pavers - Pool Deck										
Filtration Refurbishment Allowance										
Pool Lift										
Pool Resurfacing/Tile							26,628			
Swimming Pool - Phase I Total:							26,628			

	31-32	32-33	33-34	34-35	35-36	36-37	37-38	38-39	39-40	40-41
Description										
Swimming Pool - Phase II										
Concrete Pavers - Pool Deck										
Filtration Refurbishment Allowance										
Pool Lift		7,348								
Pool Resurfacing										
Pool Slide & Tower Refurbishment Allowance		26,242								
Wood Pergola							13,227			
Swimming Pool - Phase II Total:		33,589					13,227			
Playground										
Plastic Mulch Border			6,746							
Play Equipment Allowance			,							
Site Furnishing Allowance										
Swings - Tripod 2 Bay										
Playground Total:			6,746							
Components Not Included										
Electrical Panels/Wiring	Unfunded									
Fire Detection System	Unfunded									
Message Board	Unfunded									
Pool Furniture Full Replacement	Unfunded									
Pool Pumps/Equip Partial Replacement	Unfunded									
Site Utilities	Unfunded									
Water Coolers - Cabana	Unfunded									
Year Total:		54,583	77,834	4,367		4,345	74,329	81,528	4,679	

	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51
Beginning Balance	493,474	450,073	455,917	264,933	319,686	356,601	413,846	255,711	282,408	287,536
Annual Assessment	48,160	48,882	49,616	51,588	52,362	53,148	53,945	54,754	55,575	56,409
Interest Earned	4,456	4,514	2,623	3,165	3,531	4,097	2,532	2,796	2,847	3,375
Expenditures	96,017	47,552	243,224		18,978		214,611	30,853	53,294	6,483
Fully Funded Reserves	501,034	516,029	332,116	394,222	439,773	507,295	357,940	394,653	410,766	476,785
Percent Fully Funded	90%	88%	80%	81%	81%	82%	71%	72%	70%	71%
Ending Balance	450,073	455,917	264,933	319,686	356,601	413,846	255,711	282,408	287,536	340,837
Description										
Misc. Site Components										
Asphalt Mill & Overlay - Parking Lot										
Landscape & Irrigation Allowance			8,608					9,739		
Light Pole - Parking Lot										
Monument Sign Refurbishment Allowance			5,165							
Misc. Site Components Total:			13,773					9,739		
Storm Water System										
Stormwater Pond Allowance			25,824							
Storm Water System Total:			25,824							
Fencing & Gates										
Aluminum Fencing - Cabana		30,474								
Aluminum Fencing - Clubhouse										
Aluminum Fencing - Playground										
Fencing & Gates Total:		30,474								
Misc. Building Components										
Cabinets/Tops - Clubhouse Addition										
Restroom Renovation - Cabana							22,804			
Restroom Renovation - Clubhouse			24,102							
Water Coolers - Clubhouse			3,374							
Window & Door Allowance										
Misc. Building Components Total:			27,476				22,804			

	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51
Description										
Roofing										
Asphalt Shingles - Cabana										
Asphalt Shingles - Clubhouse										
Asphalt Shingles - Clubhouse Addition										
Roofing Total:										
Painting										
Exterior Painting - Cabana	3,861								4,704	
Exterior Painting - Clubhouse					10,326					
Exterior Painting - Clubhouse Addition		5,321								6,483
Painting Total:	3,861	5,321			10,326				4,704	6,483
Flooring										
Carpet - Fitness					3,226					
Flooring Allowance - Clubhouse Addition								15,271		
Flooring Total:					3,226			15,271		
Furniture Fixtures & Equipment										
Access Control/Camera Allowance			6,886							
Fitness Equipment Allowance		6,718					7,601			
Pool Furniture Allowance		5,039			5,426			5,843		
Furniture Fixtures & Equipment Total:		11,757	6,886		5,426		7,601	5,843		
HVAC										
Heat Pump - Clubhouse Addition										
Heat Pump- Fitness									12,778	
HVAC Total:									12,778	
Swimming Pool - Phase I										
Concrete Pavers - Pool Deck			27,752							
Filtration Refurbishment Allowance			43,039							
Pool Lift			9,641						27.015	
Pool Resurfacing/Tile			00.426						35,812	
Swimming Pool - Phase I Total:			80,432						35,812	

	41-42	42-43	43-44	44-45	45-46	46-47	47-48	48-49	49-50	50-51
Description										
Swimming Pool - Phase II										
Concrete Pavers - Pool Deck							88,052			
Filtration Refurbishment Allowance							47,507			
Pool Lift							10,642			
Pool Resurfacing	92,156									
Pool Slide & Tower Refurbishment Allowance							38,006			
Wood Pergola										
Swimming Pool - Phase II Total:	92,156						184,207			
Playground										
Plastic Mulch Border										
Play Equipment Allowance			77,471							
Site Furnishing Allowance			5,165							
Swings - Tripod 2 Bay			6,198							
Playground Total:			88,833							
Components Not Included										
Electrical Panels/Wiring	Unfunded									
Fire Detection System	Unfunded									
Message Board	Unfunded									
Pool Furniture Full Replacement	Unfunded									
Pool Pumps/Equip Partial Replacement	Unfunded									
Site Utilities	Unfunded									
Water Coolers - Cabana	Unfunded									
Year Total:	96,017	47,552	243,224		18,978		214,611	30,853	53,294	6,483

Description	Expenditures
Replacement Year 21-22	
Painting	
Exterior Painting - Clubhouse	5,709
Flooring	
Carpet - Fitness	1,784
Furniture Fixtures & Equipment	
Pool Furniture Allowance	3,000
Total for 2021 - 2022	<del>\$10,493</del>
Replacement Year 22-23	
Furniture Fixtures & Equipment	
Fitness Equipment Allowance	4,100
Total for 2022 - 2023	<b>\$4,100</b>
Replacement Year 23-24	
Misc. Site Components	
Landscape & Irrigation Allowance	5,253
Monument Sign Refurbishment Allowance	3,152
Total for 2023 - 2024	\$8,405
Replacement Year 24-25	
Furniture Fixtures & Equipment	
Pool Furniture Allowance	3,231
Total for 2024 - 2025	\$3,231
Replacement Year 25-26	
Painting	
Exterior Painting - Cabana	2,601
HVAC	
Heat Pump- Fitness	7,064
Swimming Pool - Phase I	
Pool Resurfacing/Tile	19,800
Total for 2025 - 2026	<del>\$29,465</del>

Description	Expenditures
Replacement Year 26-27	
Painting	
Exterior Painting - Clubhouse Addition	3,584
Total for 2026 - 2027	<del>\$3,584</del>
	Ψυ,υυ.
Replacement Year 27-28	
Furniture Fixtures & Equipment	
Fitness Equipment Allowance	4,639
Pool Furniture Allowance	3,479
Total for 2027 - 2028	\$8,118
Replacement Year 28-29	
Misc. Site Components	
Landscape & Irrigation Allowance	5,943
Storm Water System	
Stormwater Pond Allowance	17,830
Misc. Building Components	
Restroom Renovation - Clubhouse	16,642
Water Coolers - Clubhouse	2,330
Furniture Fixtures & Equipment	
Access Control/Camera Allowance	4,755
Swimming Pool - Phase I	
Pool Lift	6,657
Playground	
Play Equipment Allowance	53,491
Site Furnishing Allowance	3,566
Swings - Tripod 2 Bay	4,279
Total for 2028 - 2029	<del>\$115,493</del>
Replacement Year 29-30	
Painting	
Exterior Painting - Clubhouse	6,956
Flooring	,
Carpet - Fitness	2,173
1	,

Description	Expenditures
Replacement Year 29-30 continued	
Swimming Pool - Phase II	
Pool Resurfacing	68,523
Total for 2029 - 2030	<del>\$77,652</del>
Replacement Year 30-31	
Furniture Fixtures & Equipment	
Pool Furniture Allowance	3,747
Total for 2030 - 2031	<del>\$3,747</del>
No Replacement in 31-32	
Replacement Year 32-33	
Misc. Building Components	
Restroom Renovation - Cabana	15,745
Furniture Fixtures & Equipment	
Fitness Equipment Allowance	5,248
Swimming Pool - Phase II	
Pool Lift	7,348
Pool Slide & Tower Refurbishment Allowance	26,242
Total for 2032 - 2033	\$54,583
Replacement Year 33-34	
Misc. Site Components	
Asphalt Mill & Overlay - Parking Lot	25,488
Landscape & Irrigation Allowance	6,724
Monument Sign Refurbishment Allowance	4,035
Roofing Asphalt Shingles - Clubhouse	17,094
Painting	17,001
Exterior Painting - Cabana	3,169
Flooring	
Flooring Allowance - Clubhouse Addition	10,544
Furniture Fixtures & Equipment	
Pool Furniture Allowance	4,035

Description	Expenditures
Replacement Year 33-34 continued	
Playground	
Plastic Mulch Border	6,746
Total for 2033 - 2034	\$77,834
Replacement Year 34-35	
Painting	
Exterior Painting - Clubhouse Addition	4,367
Total for 2034 - 2035	<del>\$4,367</del>
No Replacement in 35-36	
Replacement Year 36-37	
Furniture Fixtures & Equipment	
Pool Furniture Allowance	4,345
Total for 2036 - 2037	\$4,345
Replacement Year 37-38	
Roofing	
Asphalt Shingles - Cabana	7,912
Painting	
Exterior Painting - Clubhouse	8,475
Flooring	
Carpet - Fitness	2,648
Furniture Fixtures & Equipment Fitness Equipment Allowance	5,938
HVAC	
Heat Pump- Fitness	9,501
Swimming Pool - Phase I	
Pool Resurfacing/Tile	26,628
Swimming Pool - Phase II	
Wood Pergola	13,227
Total for 2037 - 2038	\$74,329


Description	Expenditures
Replacement Year 38-39	
Misc. Site Components	
Landscape & Irrigation Allowance	7,608
Light Pole - Parking Lot	10,043
Fencing & Gates	
Aluminum Fencing - Clubhouse	11,613
Aluminum Fencing - Playground	13,037
Misc. Building Components	
Cabinets/Tops - Clubhouse Addition	4,565
Window & Door Allowance	13,695
Roofing	
Asphalt Shingles - Clubhouse Addition	11,230
HVAC	,
Heat Pump - Clubhouse Addition	9,738
Total for 2038 - 2039	<del>\$81,528</del>
10tai 101 2030 - 2037	ψ01,520
Replacement Year 39-40	
Furniture Fixtures & Equipment	
Pool Furniture Allowance	4,679
Total for 2039 - 2040	\$4,679
	,
No Replacement in 40-41	
Donlogoment Veen 41 42	
Replacement Year 41-42	
Painting	2.061
Exterior Painting - Cabana	3,861
Swimming Pool - Phase II	00.47.5
Pool Resurfacing	92,156
Total for 2041 - 2042	\$96,017
Replacement Year 42-43	
Fencing & Gates	
Aluminum Fencing - Cabana	30,474
Painting	20,171
Exterior Painting - Clubhouse Addition	5,321
Zitterior running Charles reaction	3,321

Replacement Year 42-43 continued           Furniture Fixtures & Equipment           Fitness Equipment Allowance         6,718           Pool Furniture Allowance         5,039           Total for 2042 - 2043         \$47,552           Replacement Year 43-44           Misc. Site Components           Landscape & Irrigation Allowance         8,608           Monument Sign Refurbishment Allowance         8,608           Storm Water System         25,824           Misc. Building Components         24,102           Restroom Renovation - Clubhouse         24,102           Water Coolers - Clubhouse         24,102           Water Coolers - Clubhouse         24,102           Furniture Fixtures & Equipment           Access Control/Camera Allowance         6,886           Swimming Pool - Phase I           Concrete Pavers - Pool Deck         27,752           Filtration Refurbishment Allowance         43,039           Pool Lift         9,641           Play Equipment Allowance         77,471           Site Furnishing Allowance         5,165           Swings - Tripod 2 Bay	Description	Expenditures
Fitness Equipment Allowance         5,039           Total for 2042 - 2043         \$47,552           Replacement Year 43-44         ****           Misc. Site Components         ****           Landscape & Irrigation Allowance         8,608           Monument Sign Refurbishment Allowance         5,165           Storm Water System         ***           Storm Water Pond Allowance         25,824           Misc. Building Components         ***           Restroom Renovation - Clubhouse         24,102           Water Coolers - Clubhouse         3,374           Furniture Fixtures & Equipment         6,886           Swimming Pool - Phase I         ***           Concrete Pavers - Pool Deck         27,752           Filtration Refurbishment Allowance         43,039           Pool Lift         9,641           Playground         ***           Play Equipment Allowance         5,165           Swings - Tripod 2 Bay         6,198           Total for 2043 - 2044         \$**           No Replacement in 44-45           Replacement Year 45-46           Painting         ***           Exterior Painting - Clubhouse         10,326           Flooring         ***	Replacement Year 42-43 continued	
Pool Furniture Allowance         5,039           Total for 2042 - 2043         \$47,552           Replacement Year 43-44         **** Misc. Site Components	Furniture Fixtures & Equipment	
Total for 2042 - 2043         \$47,552           Replacement Year 43-44           Misc. Site Components           Landscape & Irrigation Allowance         8,608           Monument Sign Refurbishment Allowance         5,165           Storm Water System           Storm Water Pond Allowance         25,824           Misc. Building Components           Restroom Renovation - Clubhouse         24,102           Water Coolers - Clubhouse         3,374           Furniture Fixtures & Equipment           Access Control/Camera Allowance         6,886           Swimming Pool - Phase I         27,752           Filtration Refurbishment Allowance         27,752           Filtration Refurbishment Allowance         43,039           Pool Lift         9,641           Playground         77,471           Site Furnishing Allowance         5,165           Swings - Tripod 2 Bay         6,198           Total for 2043 - 2044         \$243,224           No Replacement in 44-45         \$243,224           Replacement Year 45-46         Painting           Exterior Painting - Clubhouse         10,326           Flooring		6,718
Replacement Year 43-44           Misc. Site Components         3,608           Landscape & Irrigation Allowance         8,608           Monument Sign Refurbishment Allowance         5,165           Storm Water System         25,824           Misc. Building Components         24,102           Restroom Renovation - Clubhouse         24,102           Water Coolers - Clubhouse         3,374           Furniture Fixtures & Equipment         6,886           Swimming Pool - Phase I         27,752           Concrete Pavers - Pool Deck         27,752           Filtration Refurbishment Allowance         43,039           Pool Lift         9,641           Playground         7           Play Equipment Allowance         77,471           Site Furnishing Allowance         5,165           Swings - Tripod 2 Bay         6,198           Total for 2043 - 2044         \$243,224           No Replacement in 44-45         Replacement Year 45-46           Painting         Exterior Painting - Clubhouse         10,326           Flooring         10,326	Pool Furniture Allowance	5,039
Misc. Site Components         8,608           Landscape & Irrigation Allowance         5,165           Storm Water System         25,824           Misc. Building Components         24,102           Restroom Renovation - Clubhouse         24,102           Water Coolers - Clubhouse         3,374           Furniture Fixtures & Equipment         6,886           Access Control/Camera Allowance         6,886           Swimming Pool - Phase I         27,752           Filtration Refurbishment Allowance         43,039           Pool Lift         9,641           Playground         77,471           Site Furnishing Allowance         5,165           Swings - Tripod 2 Bay         6,198           Total for 2043 - 2044         \$243,224           No Replacement in 44-45         \$243,224           Replacement Year 45-46         Painting           Exterior Painting - Clubhouse         10,326           Flooring         10,326	Total for 2042 - 2043	\$47,552
Landscape & Irrigation Allowance       8,608         Monument Sign Refurbishment Allowance       5,165         Storm Water System <ul> <li>Stormwater Pond Allowance</li> <li>25,824</li> </ul> Misc. Building Components <ul> <li>Restroom Renovation - Clubhouse</li> <li>24,102</li> <li>Water Coolers - Clubhouse</li> <li>3,374</li> </ul> Furniture Fixtures & Equipment <ul> <li>Access Control/Camera Allowance                       <li>6,886</li> <li>Swimming Pool - Phase I                       <li>Concrete Pavers - Pool Deck</li> <ul> <li>Filtration Refurbishment Allowance</li> <li>43,039</li> <li>Pool Lift</li> <li>9,641</li> </ul></li></li></ul>	Replacement Year 43-44	
Monument Sign Refurbishment Allowance         5,165           Storm Water System	Misc. Site Components	
Storm Water System         Stormwater Pond Allowance       25,824         Misc. Building Components         Restroom Renovation - Clubhouse       24,102         Water Coolers - Clubhouse       3,374         Furniture Fixtures & Equipment         Access Control/Camera Allowance       6,886         Swimming Pool - Phase I         Concrete Pavers - Pool Deck       27,752         Filtration Refurbishment Allowance       43,039         Pool Lift       9,641         Playground       77,471         Site Furnishing Allowance       5,165         Swings - Tripod 2 Bay       6,198         Total for 2043 - 2044       \$243,224         No Replacement in 44-45         Replacement Year 45-46         Painting       Exterior Painting - Clubhouse       10,326         Flooring       10,326	Landscape & Irrigation Allowance	8,608
Stormwater Pond Allowance       25,824         Misc. Building Components       24,102         Restroom Renovation - Clubhouse       3,374         Furniture Fixtures & Equipment       3,374         Access Control/Camera Allowance       6,886         Swimming Pool - Phase I       27,752         Concrete Pavers - Pool Deck       27,752         Filtration Refurbishment Allowance       43,039         Pool Lift       9,641         Playground       77,471         Site Furnishing Allowance       5,165         Swings - Tripod 2 Bay       6,198         Total for 2043 - 2044       \$243,224         No Replacement in 44-45       \$243,224         Replacement Year 45-46       Painting       10,326         Exterior Painting - Clubhouse       10,326         Flooring       10,326	Monument Sign Refurbishment Allowance	5,165
Misc. Building Components       24,102         Restroom Renovation - Clubhouse       24,102         Water Coolers - Clubhouse       3,374         Furniture Fixtures & Equipment	Storm Water System	
Restroom Renovation - Clubhouse       24,102         Water Coolers - Clubhouse       3,374         Furniture Fixtures & Equipment       3,374         Access Control/Camera Allowance       6,886         Swimming Pool - Phase I       27,752         Concrete Pavers - Pool Deck       27,752         Filtration Refurbishment Allowance       43,039         Pool Lift       9,641         Playground       77,471         Site Furnishing Allowance       5,165         Swings - Tripod 2 Bay       6,198         Total for 2043 - 2044       \$243,224         No Replacement in 44-45       \$243,224         Replacement Year 45-46       Painting         Exterior Painting - Clubhouse       10,326         Flooring       10,326	· · · · · · · · · · · · · · · · · · ·	25,824
Restroom Renovation - Clubhouse       24,102         Water Coolers - Clubhouse       3,374         Furniture Fixtures & Equipment       3,374         Access Control/Camera Allowance       6,886         Swimming Pool - Phase I       27,752         Concrete Pavers - Pool Deck       27,752         Filtration Refurbishment Allowance       43,039         Pool Lift       9,641         Playground       77,471         Site Furnishing Allowance       5,165         Swings - Tripod 2 Bay       6,198         Total for 2043 - 2044       \$243,224         No Replacement in 44-45       \$243,224         Replacement Year 45-46       Painting         Exterior Painting - Clubhouse       10,326         Flooring       10,326	Misc. Building Components	
Furniture Fixtures & Equipment	<u> </u>	24,102
Access Control/Camera Allowance       6,886         Swimming Pool - Phase I       27,752         Concrete Pavers - Pool Deck       27,752         Filtration Refurbishment Allowance       43,039         Pool Lift       9,641         Playground       77,471         Site Furnishing Allowance       5,165         Swings - Tripod 2 Bay       6,198         Total for 2043 - 2044       \$243,224         No Replacement in 44-45       \$243,224         Replacement Year 45-46       Fainting         Exterior Painting - Clubhouse       10,326         Flooring       10,326	Water Coolers - Clubhouse	3,374
Access Control/Camera Allowance       6,886         Swimming Pool - Phase I       27,752         Concrete Pavers - Pool Deck       27,752         Filtration Refurbishment Allowance       43,039         Pool Lift       9,641         Playground       77,471         Site Furnishing Allowance       5,165         Swings - Tripod 2 Bay       6,198         Total for 2043 - 2044       \$243,224         No Replacement in 44-45       \$243,224         Replacement Year 45-46       Fainting         Exterior Painting - Clubhouse       10,326         Flooring       10,326	Furniture Fixtures & Equipment	
Concrete Pavers - Pool Deck Filtration Refurbishment Allowance Pool Lift Playground Play Equipment Allowance Swings - Tripod 2 Bay Total for 2043 - 2044  Replacement in 44-45  Replacement Year 45-46  Painting Exterior Painting - Clubhouse Flooring  27,752 43,039 43,03		6,886
Concrete Pavers - Pool Deck Filtration Refurbishment Allowance Pool Lift Playground Play Equipment Allowance Swings - Tripod 2 Bay Total for 2043 - 2044  Replacement in 44-45  Replacement Year 45-46  Painting Exterior Painting - Clubhouse Flooring  27,752 43,039 43,03	Swimming Pool - Phase I	
Pool Lift 9,641  Playground Play Equipment Allowance 77,471 Site Furnishing Allowance 5,165 Swings - Tripod 2 Bay 6,198  Total for 2043 - 2044 \$243,224  No Replacement in 44-45  Replacement Year 45-46  Painting Exterior Painting - Clubhouse 10,326  Flooring	e	27,752
Play Equipment Allowance 77,471 Site Furnishing Allowance 5,165 Swings - Tripod 2 Bay 6,198  Total for 2043 - 2044 \$243,224  No Replacement in 44-45  Replacement Year 45-46  Painting Exterior Painting - Clubhouse 10,326  Flooring	Filtration Refurbishment Allowance	43,039
Play Equipment Allowance 77,471 Site Furnishing Allowance 5,165 Swings - Tripod 2 Bay 6,198  Total for 2043 - 2044 \$243,224  No Replacement in 44-45  Replacement Year 45-46  Painting Exterior Painting - Clubhouse 10,326  Flooring	Pool Lift	9,641
Play Equipment Allowance 77,471 Site Furnishing Allowance 5,165 Swings - Tripod 2 Bay 6,198  Total for 2043 - 2044 \$243,224  No Replacement in 44-45  Replacement Year 45-46  Painting Exterior Painting - Clubhouse 10,326  Flooring	Playground	
Swings - Tripod 2 Bay  Total for 2043 - 2044  No Replacement in 44-45  Replacement Year 45-46  Painting Exterior Painting - Clubhouse  Flooring	• •	77,471
Total for 2043 - 2044 \$243,224  No Replacement in 44-45  Replacement Year 45-46  Painting Exterior Painting - Clubhouse 10,326  Flooring	Site Furnishing Allowance	5,165
No Replacement in 44-45  Replacement Year 45-46  Painting Exterior Painting - Clubhouse 10,326  Flooring	Swings - Tripod 2 Bay	6,198
Replacement Year 45-46  Painting Exterior Painting - Clubhouse 10,326  Flooring	Total for 2043 - 2044	\$243,224
Painting Exterior Painting - Clubhouse 10,326 Flooring	No Replacement in 44-45	
Exterior Painting - Clubhouse 10,326  Flooring	Replacement Year 45-46	
Exterior Painting - Clubhouse 10,326  Flooring	Painting	
		10,326
	Flooring	
5,==0	Carpet - Fitness	3,226

Description	Expenditures
Replacement Year 45-46 continued	
Furniture Fixtures & Equipment	
Pool Furniture Allowance	5,426
Total for 2045 - 2046	<b>\$18,978</b>
No Replacement in 46-47	
Replacement Year 47-48	
Misc. Building Components	
Restroom Renovation - Cabana	22,804
Furniture Fixtures & Equipment	
Fitness Equipment Allowance	7,601
Swimming Pool - Phase II	
Concrete Pavers - Pool Deck	88,052
Filtration Refurbishment Allowance	47,507
Pool Lift Pool Slide & Tower Refurbishment Allowance	10,642 38,006
Total for 2047 - 2048	\$214,611
Replacement Year 48-49	
Misc. Site Components	
Landscape & Irrigation Allowance	9,739
Flooring	
Flooring Allowance - Clubhouse Addition	15,271
Furniture Fixtures & Equipment	
Pool Furniture Allowance	5,843
Total for 2048 - 2049	\$30,853
Replacement Year 49-50	
Painting	
Exterior Painting - Cabana	4,704
HVAC	
Heat Pump- Fitness	12,778
Swimming Pool - Phase I	
Pool Resurfacing/Tile	35,812
Total for 2049 - 2050	\$53,294

Description	Expenditures
Replacement Year 50-51	
Painting	
Exterior Painting - Clubhouse Addition	6,483
Total for 2050 - 2051	\$6,483

#### Ridgewood Trails Community Development District Asset Current Cost by Category



	~	ల త్ర	st Soli		raeni.	igiso		æ
Description	Out Styl	50 76	\$ 25E	P Sill	şir Qenna	Jülis	उत्में एक	Children Con Con Con Con Con Con Con Con Con Co
Misc. Site Components								
Asphalt Mill & Overlay - Parking Lot	2014	33-34	20	0	12	920 Square Yards	20.60	18,952
Landscape & Irrigation Allowance	2017	23-24	5	2	2	1 Lump Sum	5,000.00	5,000
Light Pole - Parking Lot Monument Sign Refurbishment Allowance	2014 2014	38-39 23-24	25 10	0	17 2	3 Each 1 Lump Sum	2,200.00 3,000.00	6,600 3,000
Misc. Site Components - Total	2014	23-24	10	U	2	1 Lump Sum	3,000.00	\$33,552
Storm Water System								
Stormwater Pond Allowance	2014	28-29	15	0	7	1 Lump Sum	15,000.00	_15,000
Storm Water System - Total								\$15,000
Fencing & Gates								
Aluminum Fencing - Cabana	2018	42-43	25	0	21	504 Linear Feet	36.00	18,144
Aluminum Fencing - Clubhouse	2014	38-39	25	0	17	212 Linear Feet	36.00	7,632
Aluminum Fencing - Playground Fencing & Gates - Total	2014	38-39	25	0	17	238 Linear Feet	36.00	8,568 \$34,344
Mice Puilding Components								
Misc. Building Components Cabinets/Tops - Clubhouse Addition	2019	38-39	20	0	17	1 Lump Sum	3,000.00	3,000
Restroom Renovation - Cabana	2019	32-33	15	0	11	1 Lump Sum	12,000.00	12,000
Restroom Renovation - Clubhouse	2014	28-29	15	0	7	1 Lump Sum	14,000.00	14,000
Water Coolers - Clubhouse	2014	28-29	15	0	7	2 Each	980.00	1,960
Window & Door Allowance	2014	38-39	25	0	17	1 Lump Sum	9,000.00	9,000
Misc. Building Components - Total						<b>r</b>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	\$39,960
Roofing								
Asphalt Shingles - Cabana	2018	37-38	20	0	16	13 Squares	410.00	5,330
Asphalt Shingles - Clubhouse	2014	33-34	20	0	12	31 Squares	410.00	12,710
Asphalt Shingles - Clubhouse Addition	2019	38-39	20	0	17	18 Squares	410.00	7,380
Roofing - Total								\$25,420
Painting								
Exterior Painting - Cabana	2018	25-26	8	0	4	1,428 Square Feet	1.65	2,356
Exterior Painting - Clubhouse	2014	21-22	8	0	0	3,460 Square Feet	1.65	5,709
Exterior Painting - Clubhouse Addition Painting - Total	2019	26-27	8	0	5	1,920 Square Feet	1.65	3,168 \$11,233
								Ψ11,233
Flooring								
Carpet - Fitness	2014	21-22	8	0	0	49 Square Yards	36.40	1,784
Flooring Allowance - Clubhouse Addition Flooring - Total	2019	33-34	15	0	12	1,600 Square Feet	4.90	<u>7,840</u> \$9,624
Furniture Fixtures & Equipment								
Access Control/Camera Allowance	2014	28-29	15	0	7	1 Lump Sum	4,000.00	4,000

		4	de di		.ent	. 0 <sup>0</sup> 0		
<b></b>	Operation of	ş <sup>©</sup> 4 <sup>©</sup>	ي مهريون	· 18	A South	Odis Odis	Jan Jose	California California
Description	2, %	\$ 7	2	S.	\$3	Ø,	\$ 6	0.0
Furniture Fixtures & Equipment continued								
Fitness Equipment Allowance	2018	22-23	5	0	1	1 Lump Sum	4,000.00	4,000
Pool Furniture Allowance	2018	21-22	3	0	0	1 Lump Sum	3,000.00	3,000 \$11,000
Furniture Fixtures & Equipment - Total								\$11,000
HVAC								
Heat Pump - Clubhouse Addition	2019	38-39	20	0	17	4 Ton	1,600.00	6,400
Heat Pump- Fitness	2014	25-26	12	0	4	4 Ton	1,600.00	6,400
HVAC - Total								\$12,800
Cwimming Dool Dhogo I								
Swimming Pool - Phase I Concrete Pavers - Pool Deck	2014	43-44	30	0	22	2,015 Square Feet	8.00	16,120
Filtration Refurbishment Allowance	2014	43-44	30	0	22	1 Lump Sum	25,000.00	25,000
Pool Lift	2014	28-29	15	0	7	1 Each	5,600.00	5,600
Pool Resurfacing/Tile	2014	25-26	12	0	4	1,212 Square Feet	14.80	17,938
Swimming Pool - Phase I - Total						•		\$64,658
Carina David Diana II								
Swimming Pool - Phase II Concrete Pavers - Pool Deck	2010	47.40	20	0	26	5 700 C Fran	0.00	46 226
Filtration Refurbishment Allowance	2018 2018	47-48 47-48	30 30	0	26 26	5,792 Square Feet 1 Lump Sum	8.00 25,000.00	46,336 25,000
Pool Lift	2018	32-33	15	0	11	1 Each	5,600.00	5,600
Pool Resurfacing	2018	29-30	12	0	8	3,800 Square Feet	14.80	56,240
Pool Slide & Tower Refurbishment Allowan		32-33	15	0	11	1 Lump Sum	20,000.00	20,000
Wood Pergola	2018	37-38	20	0	16	3 Each	2,970.00	8,910
Swimming Pool - Phase II - Total								\$162,086
Dlayground								
Playground Plastic Mulch Border	2014	33-34	20	0	12	228 Linear Feet	22.00	5,016
Play Equipment Allowance	2014	28-29	15	0	7	1 Lump Sum	45,000.00	45,000
Site Furnishing Allowance	2014	28-29	15	0	7	1 Lump Sum	3,000.00	3,000
Swings - Tripod 2 Bay	2014	28-29	15	0	7	1 Each	3,600.00	3,600
Playground - Total								\$56,616
Components Not Included								
Electrical Panels/Wiring	17	nfunded						
Fire Detection System		nfunded						
Message Board		nfunded						
Pool Furniture Full Replacement		nfunded						
Pool Pumps/Equip Partial Replacement	$U_i$	nfunded						
Site Utilities		nfunded						
Water Coolers - Cabana	$U_{i}$	nfunded						
Components Not Included - Total								
Total Asset Summary								\$476,292
·····								+ · · · · · · · · · · · · · · · · · · ·

Asset II	DDescription	Replacement	Page
Misc. S	ite Components		
1037	Asphalt Mill & Overlay - Parking Lot	33-34	5-5
1074	Landscape & Irrigation Allowance	23-24	5-5
1068	Light Pole - Parking Lot	38-39	5-5
1003	Monument Sign Refurbishment Allowance	23-24	5-6
Storm '	Water System		
1049	Stormwater Pond Allowance	28-29	5-7
Fencing	g & Gates		
1071	Aluminum Fencing - Cabana	42-43	5-8
1006	Aluminum Fencing - Clubhouse	38-39	5-8
1067	Aluminum Fencing - Playground	38-39	5-9
Misc. B	Building Components		
1083	Cabinets/Tops - Clubhouse Addition	38-39	5-10
1062	Restroom Renovation - Cabana	32-33	5-10
1064	Restroom Renovation - Clubhouse	28-29	5-11
1073	Water Coolers - Clubhouse	28-29	5-11
1007	Window & Door Allowance	38-39	5-12
Roofing	<u> </u>		
1066	Asphalt Shingles - Cabana	37-38	5-13
1001	Asphalt Shingles - Clubhouse	33-34	5-13
1081	Asphalt Shingles - Clubhouse Addition	38-39	5-14
Paintin	g		
1056	Exterior Painting - Cabana	25-26	5-15
1005	Exterior Painting - Clubhouse	21-22	5-15
1080	Exterior Painting - Clubhouse Addition	26-27	5-16
Floorin	g		
1031	Carpet - Fitness	21-22	5-17
1082	Flooring Allowance - Clubhouse Addition	33-34	5-17
Furnitu	ıre Fixtures & Equipment		
1012	Access Control/Camera Allowance	28-29	5-18
1032	Fitness Equipment Allowance	22-23	5-18
	1 1		-

Asset II	DDescription	Replacement	Page
Furnitu	re Fixtures & Equipment Continued		
1021	Pool Furniture Allowance	21-22	5-19
HVAC			
1084	Heat Pump - Clubhouse Addition	38-39	5-20
1011	Heat Pump- Fitness	25-26	5-20
Swimm	ing Pool - Phase I		
1019	Concrete Pavers - Pool Deck	43-44	5-21
1076	Filtration Refurbishment Allowance	43-44	5-21
1065	Pool Lift	28-29	5-22
1029	Pool Resurfacing/Tile	25-26	5-22
	ing Pool - Phase II		
1057	Concrete Pavers - Pool Deck	47-48	5-23
1077	Filtration Refurbishment Allowance	47-48	5-23
1028	Pool Lift	32-33	5-24
1060	Pool Resurfacing	29-30	5-24
1061	Pool Slide & Tower Refurbishment Allowance	32-33	5-25
1058	Wood Pergola	37-38	5-25
Playgro	aund		
1033	Plastic Mulch Border	33-34	5-26
1035	Play Equipment Allowance	28-29	5-26
1069	Site Furnishing Allowance	28-29	5-27
1034	Swings - Tripod 2 Bay	28-29	5-27
Compo	nents Not Included		
1079	Electrical Panels/Wiring	Unfunded	5-28
1014	Fire Detection System	Unfunded	5-28
1078	Message Board	Unfunded	5-28
1086	Pool Furniture Full Replacement	Unfunded	5-29
1075	Pool Pumps/Equip Partial Replacement	Unfunded	5-29
1085	Site Utilities	Unfunded	5-29
1063	Water Coolers - Cabana	Unfunded	5-30
	Total Funded Assets	40	
	Total Unfunded Assets Total Unfunded Assets	40	
		$\frac{7}{47}$	
	Total Assets	4/	

#### Asphalt Mill & Overlay - Parking Lot - 2033

 Asset ID
 1037
 Asset Actual Cost Percent Replacement
 \$18,952.00

 Misc. Site Components
 Future Cost
 \$25,488.33

Placed in Service January 2014
Useful Life 20
Replacement Year 33-34
Remaining Life 12



#### Landscape & Irrigation Allowance - 2023

1 Lump Sum @ \$5,000.00 Asset ID 1074 **Asset Actual Cost** \$5,000.00 Percent Replacement 100% Misc. Site Components **Future Cost** \$5,253.12 Placed in Service January 2017 Useful Life 5 2 Adjustment

23-24

2

Light Pole - Parking Lot - 2038

Replacement Year

Remaining Life

Asset ID 1068 Asset Actual Cost \$6,600.00

Percent Replacement 100%

Misc. Site Components Future Cost \$10,042.68

Placed in Service January 2014
Useful Life 25
Replacement Year 38-39

Remaining Life 17

Community Advisors Page 5-5 January 15, 2021

Light Pole - Parking Lot continued...



#### Monument Sign Refurbishment Allowance - 2023

			1 Lump Sum	@ \$3,000.00
	Asset ID	1003	Asset Actual Cost	\$3,000.00
			Percent Replacement	100%
	Misc. Site Components		Future Cost	\$3,151.87
-	1	T 0011		

Placed in Service January 2014
Useful Life 10
Replacement Year 23-24
Remaining Life 2



# Stormwater Pond Allowance - 2028

Asset ID	1049	1 Lump Sum Asset Actual Cost Percent Replacement	@ \$15,000.00 \$15,000.00 100%
	Storm Water System	Future Cost	\$17,830.29
Placed in Service	January 2014		
Useful Life	15		
Replacement Year	28-29		
Remaining Life	7		

#### Aluminum Fencing - Cabana - 2042

Asset ID 1071 Asset Actual Cost \$18,144.00
Percent Replacement 100%
Fencing & Gates Future Cost \$30,474.33

Placed in Service
Useful Life
25
Replacement Year
Remaining Life
June 2018
42-43
21



#### Aluminum Fencing - Clubhouse - 2038

Asset ID 1006 Asset Actual Cost \$7,632.00
Percent Replacement 100%
Fencing & Gates Future Cost \$11,612.99

Placed in Service
Useful Life
25
Replacement Year
Remaining Life
January 2014
25
38-39



Community Advisors Page 5-8 January 15, 2021

# Aluminum Fencing - Playground - 2038

Asset ID	1067	238 Linear Feet Asset Actual Cost Percent Replacement	@ \$36.00 \$8,568.00 100%
	Fencing & Gates	Future Cost	\$13,037.22
Placed in Service	January 2014		
Useful Life	25		
Replacement Year	38-39		
Remaining Life	17		



#### Cabinets/Tops - Clubhouse Addition - 2038

Asset ID 1083 Asset Actual Cost \$3,000.00
Percent Replacement 100%
Misc. Building Components Future Cost \$4,564.85

Placed in Service
Useful Life

Replacement Year
Remaining Life

January 2019
20
38-39
Remaining Life



#### Restroom Renovation - Cabana - 2032

Asset ID 1062 Asset Actual Cost \$12,000.00
Percent Replacement 100%
Misc. Building Components Future Cost \$15,745.04

Placed in Service
Useful Life
Useful Life
Replacement Year
Remaining Life
June 2018
32-33
15
11



Community Advisors Page 5-10 January 15, 2021

## Restroom Renovation - Clubhouse - 2028

1 Lump Sum @ \$14,000.00 Asset ID 1064 Asset Actual Cost \$14,000.00 Percent Replacement 100% Misc. Building Components **Future Cost** \$16,641.60

January 2014 Placed in Service Useful Life 15 Replacement Year 28-29 Remaining Life 7



# Water Coolers - Clubhouse - 2028

Asset ID 1073 Asset Actual Cost

\$1,960.00 Percent Replacement 100% Misc. Building Components **Future Cost** \$2,329.82 Placed in Service January 2014

@ \$980.00

2 Each

Useful Life 15 Replacement Year 28-29 Remaining Life 7



Community Advisors Page 5-11 January 15, 2021

# Window & Door Allowance - 2038

Asset ID 1007

Misc. Building Components
Placed in Service January 2014
Useful Life 25
Replacement Year 38-39

Remaining Life 17



# Asphalt Shingles - Cabana - 2037

 ngles - Cabana - 2037
 13 Squares
 @ \$410.00

 Asset ID
 1066
 Asset Actual Cost
 \$5,330.00

 Percent Replacement
 100%

 Roofing
 Future Cost
 \$7,912.41

Placed in Service April 2018
Useful Life 20
Replacement Year 37-38
Remaining Life 16



# Asphalt Shingles - Clubhouse - 2033

 Asset ID
 1001
 Asset Actual Cost Percent Replacement
 \$12,710.00

 Roofing
 Future Cost
 \$17,093.54

Placed in Service
Useful Life

Replacement Year
Remaining Life

January 2014
20
33-34
Remaining Life



Community Advisors Page 5-13 January 15, 2021

# Asphalt Shingles - Clubhouse Addition - 2038

Asset ID	1081	18 Squares Asset Actual Cost Percent Replacement	@ \$410.00 \$7,380.00 100%
	Roofing	Future Cost	\$11,229.54
Placed in Service	January 2019		
Useful Life	20		
Replacement Year	38-39		
Remaining Life	17		



# Exterior Painting - Cabana - 2025

1,428 Square Feet Asset ID 1056 Asset Actual Cost \$2,356.20 Percent Replacement 100%

**Future Cost** 

@ \$1.65

\$2,600.80

**Painting** Placed in Service April 2018 Useful Life Replacement Year 25-26 Remaining Life 4



# Exterior Painting - Clubhouse - 2021

3,460 Square Feet @ \$1.65 Asset Actual Cost Asset ID 1005 \$5,709.00 Percent Replacement 100% **Painting Future Cost** \$5,709.00

Placed in Service January 2014 Useful Life Replacement Year 21-22 Remaining Life 0



Community Advisors Page 5-15 January 15, 2021

# Exterior Painting - Clubhouse Addition - 2026

Asset ID	1080	1,920 Square Feet Asset Actual Cost Percent Replacement	@ \$1.65 \$3,168.00 100%
	Painting	Future Cost	\$3,584.30
Placed in Service	January 2019		
Useful Life	8		
Replacement Year	26-27		
Remaining Life	5		



# Carpet - Fitness - 2021

49 Square Yards @ \$36.40 Asset ID 1031 **Asset Actual Cost** \$1,783.60 Percent Replacement 100% Flooring **Future Cost** \$1,783.60

January 2014 Placed in Service Useful Life Replacement Year 21-22 Remaining Life 0



# Flooring Allowance - Clubhouse Addition - 2033

1,600 Square Feet @ \$4.90 Asset ID 1082 Asset Actual Cost \$7,840.00 Percent Replacement 100% Flooring **Future Cost** \$10,543.93

Placed in Service January 2019 Useful Life 15 Replacement Year 33-34 Remaining Life 12



Community Advisors Page 5-17 January 15, 2021

#### Access Control/Camera Allowance - 2028

Asset ID 1012 Asset Actual Cost \$4,000.00
Percent Replacement Future Fixtures & Equipment Future Cost \$4,754.74

Placed in Service January 2014
Useful Life 15
Replacement Year 28-29
Remaining Life 7





# Fitness Equipment Allowance - 2022

Asset ID 1032 Asset Actual Cost \$4,000.00
Percent Replacement Future Fixtures & Equipment Future Cost \$4,000.00

Placed in Service
Useful Life
September 2018
Replacement Year
Remaining Life
September 2018
22-23



Community Advisors Page 5-18 January 15, 2021

# Pool Furniture Allowance - 2021

Asset ID 1021 Asset Actual Cost Percent Replacement Furniture Fixtures & Equipment Future Cost \$3,000.00

Placed in Service
Useful Life
3
Replacement Year
Remaining Life
January 2018
21-22
0



# Heat Pump - Clubhouse Addition - 2038

- Clubhouse Addition - 2038 4 Ton @ \$1,600.00

Asset ID 1084 Asset Actual Cost \$6,400.00

Percent Replacement 100%

HVAC Future Cost \$9,738.36

Placed in Service January 2019
Useful Life 20
Replacement Year 38-39
Remaining Life 17



# Heat Pump- Fitness - 2025

Asset ID 1011 Asset Actual Cost \$6,400.00
Percent Replacement 100%
HVAC Future Cost \$7,064.40

Placed in Service January 2014
Useful Life 12
Replacement Year 25-26
Remaining Life 4



## Concrete Pavers - Pool Deck - 2043

2,015 Square Feet @ \$8.00
Asset ID 1019 Asset Actual Cost \$16,120.00
Percent Replacement 100%
Swimming Pool - Phase I Future Cost \$27,751.73

Placed in Service
Useful Life
30
Replacement Year
Remaining Life
22



## Filtration Refurbishment Allowance - 2043

Asset ID 1076 Asset Actual Cost \$25,000.00

Percent Replacement 100%

Swimming Pool - Phase I Future Cost \$43,039.28

Placed in Service January 2014
Useful Life 30
Replacement Year 43-44
Remaining Life 22



Community Advisors Page 5-21 January 15, 2021

# Pool Lift - 2028

Asset ID 1065 Asset Actual Cost \$5,600.00

Percent Replacement 100%

Swimming Pool - Phase I Future Cost \$6,656.64

Placed in Service January 2014
Useful Life 15
Replacement Year 28-29
Remaining Life 7



# Pool Resurfacing/Tile - 2025

Asset ID 1029 Asset Actual Cost \$17,937.

Percent Replacement 100

Swimming Pool - Phase I Placed in Service January 2014

Useful Life 12
Replacement Year 25-26
Remaining Life 4

 1,212 Square Feet
 @ \$14.80

 Asset Actual Cost
 \$17,937.60

 Percent Replacement
 100%

 Future Cost
 \$19,799.75



# Concrete Pavers - Pool Deck - 2047

		5,792 Square Feet	@ \$8.00
Asset ID	1057	Asset Actual Cost	\$46,336.00
		Percent Replacement	100%
Swimming Pool - Phase II		Future Cost	\$88,051.96

Placed in Service April 2018
Useful Life 30
Replacement Year 47-48
Remaining Life 26



# Filtration Refurbishment Allowance - 2047

		1 Lump Sum	@ \$25,000.00
Asset 1	ID 1077	Asset Actual Cost	\$25,000.00
		Percent Replacement	100%
Swimming Pool - Phase II		Future Cost	\$47,507.32
n Servi	ce June 2018		

Placed in Service June 2018
Useful Life 30
Replacement Year 47-48
Remaining Life 26



Community Advisors Page 5-23 January 15, 2021

# Pool Lift - 2032

Asset ID 1028 Asset Actual Cost \$5,600.00

Percent Replacement 100%

Swimming Pool - Phase II Future Cost \$7,347.68

Placed in Service
Useful Life
Useful Life
Replacement Year
Remaining Life
June 2018
32-33
15
11



# Pool Resurfacing - 2029

Asset ID 1060 Asset Actual Cost \$56,240.00 Percent Replacement 100%

3,800 Square Feet

@ \$14.80

Swimming Pool - Phase II Future Cost \$68,522.98

Placed in Service
Useful Life
Useful Life
Replacement Year
Remaining Life
June 2018
29-30
8



Community Advisors Page 5-24 January 15, 2021

# Pool Slide & Tower Refurbishment Allowance - 2032

Asset ID 1061 Asset Actual Cost \$20,000.00

Percent Replacement 100%

Swimming Pool - Phase II Future Cost \$26,241.73

Placed in Service
Useful Life
15
Replacement Year
Remaining Life
June 2018
32-33



# Wood Pergola - 2037

Asset ID 1058 Asset Actual Cost \$8,910.00
Percent Replacement 100%
Swimming Pool - Phase II Future Cost \$13,226.94

Placed in Service April 2018
Useful Life 20
Replacement Year 37-38
Remaining Life 16



# Plastic Mulch Border - 2033

Asset ID 1033

228 Linear Feet @ \$22.00 Asset Actual Cost \$5,016.00 Percent Replacement 100% Future Cost \$6,745.96

Playground
Placed in Service
Useful Life
Replacement Year
Remaining Life
Playground
January 2014
33-34
Remaining Life



# Play Equipment Allowance - 2028

Asset ID 1035

Playground
Placed in Service
Useful Life
TS
Replacement Year
Remaining Life
Playground
January 2014
28-29
7



# Site Furnishing Allowance - 2028

Asset ID 1069

Playground
Placed in Service
Useful Life
Useful Life
Replacement Year
Remaining Life
Playground
January 2014
2014
7



# Swings - Tripod 2 Bay - 2028

Asset ID 1034

Playground
Placed in Service
Useful Life
Useful Life
The Replacement Year
Remaining Life
Playground
January 2014
2014
7



# **Electrical Panels/Wiring**

Asset ID 1079 Asset Actual Cost

Percent Replacement 100% Components Not Included **Future Cost** 

Placed in Service January 2017 No Useful Life



# Fire Detection System

1014 Asset ID Asset Actual Cost Percent Replacement 100%

**Future Cost** 

Components Not Included Placed in Service January 2014

No Useful Life

## Message Board

Asset ID 1078 Asset Actual Cost

Percent Replacement 100% Components Not Included **Future Cost** 

Placed in Service January 2017 No Useful Life

Message Board continued...



# Pool Furniture Full Replacement

No Useful Life

Asset ID 1086 Asset Actual Cost

Percent Replacement 100%
Components Not Included Future Cost
Placed in Service June 2018

# Pool Pumps/Equip Partial Replacement

Asset ID 1075 Asset Actual Cost
Percent Replacement 100%
Components Not Included Future Cost

Components Not Included
Placed in Service January 2014
No Useful Life

# Site Utilities

Asset ID 1085 Asset Actual Cost

Percent Replacement 100%
Components Not Included Future Cost
Placed in Service June 2018

No Useful Life

Community Advisors Page 5-29 January 15, 2021

Water Coolers - Cabana

Asset ID 1063 Asset Actual Cost Percent Replacement

Components Not Included Future Cost

100%

Placed in Service June 2018

No Useful Life

#### **METHODOLOGY**

Reserve Analysis is a process that identifies capital expenses the District can expect and creates a plan to fund them. This is accomplished by a site visit to visually evaluate components to measure quantities and determine their remaining life. Component Selection Process is based on the Community Associations Institute (CAI) standards for reserve studies and selection of components.

Component must be a commonly owned, have a limited and predictable life, replacement cost must be above a minimum threshold cost. Useful life and replacement cost are obtained from site inspection by experienced inspectors and our database of information, historical information, local Vendors and comparison of similar component cost found at other properties.

The funding plan we develop includes; adequate cash balances, even contributions so all owners pay their fair share over time and moderate contributions with acceptable increases. Percent Funded is defined by industry standards as 70-100% strong, 30-70% fair or adequate and below 30% weak or inadequate. We recommend Full Funding if possible to avoid deferred maintenance or special assessments. Baseline Funding maintains funds above zero resulting is a high risk of special assessments or deferred maintenance and should be avoided. Threshold Funding maintains reserves above a "Threshold" level providing adequate funding with moderate risk.

#### **CREDENTIALS**

Community Advisors, LLC provides capital reserve planning, property inspection, and construction oversight for a broad base of clients including CDD communities, Condominiums, Homeowner Associations, Churches, Private Schools, Time Shares, Active Adult, Municipal Utility Plants, Marinas, Historic Buildings & Museums and commercial investment properties.

*Personal Service* is our common business practice but our attention to detail, quick response and interest in client relationships continues to earn us a larger market share of work each year.

Range of Experience includes a broad selection of building types, ages and uses from protected historic structures to new communities ready for developer turnover. As commercial general contractors we have experience building many of the types of structure we now provide reserve analysis for, so we understand potential problem areas. As commercial inspectors we have experienced a variety of structural and cosmetic conditions offering solutions for repair. Areas of expertise include MEP systems, energy management, life safety systems, building envelope and roof components, marine structures, street and other site improvements.

Detailed Site Evaluation is Conducted to make sure we know your property and include all your assets in our analysis. With our years of experience with community development and commercial construction projects we understand both horizontal and vertical construction and utilize realistic replacement cost and useful life projections in our analysis. Financial Plan Meets CAI & APRA Standards with information obtained during the site visit we build a custom-made financial plan to ensure adequate funding for future component replacement which equates to maintaining District value.

Reserve Analyst Credentials: Mr. Charles Sheppard is the owner of Community Advisors responsible for field inspection oversight and day to day operations. Mr. Sheppard hold a BS degree from VA Tech and has conducted building evaluations for over 30 years. He is a licensed Florida General Contractor, Home Inspector and earned the professional designations of Certified Construction Inspector (CCI), Professional Reserve Analyst (PRA) and Reserve Specialist (RS).

#### TERMS OF SERVICE

We have completed an analysis of your capital components that serves as a budgeting tool. This reserve study reflects the information provided by this client and is not for the purposes of performing an audit or estimating construction projects. Our site visit includes visual observation of components that are accessible and safe for our inspectors to evaluate. Roof evaluation is limited to ground observation for sloped roofs and roof top inspection for flat roofs if safe and stable access is available that meets our safety standards.

We are not responsible for any hidden defects or determining the condition of hidden or underground components or systems. Observing environmental conditions, hazardous materials or determine compliance with building codes or other regulations is not included in our scope of work. Our site visit is not a safety inspection and we are not responsible for any hazards that exist. Destructive testing is not conducted. It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications.

Projections of component remaining useful life assumes this client will perform necessary preventative maintenance and repair per industry standards. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by the Client and its contractors, assorted vendors, specialist and independent contractors. Reserve fund balances and contribution amounts for use in our analysis is furnished by the client and deemed accurate. Useful life projections are determined by historical records, component condition and our opinion based on evaluating similar components on other projects. These life projections are changed by weather conditions, use, maintenance procedures and other factors out of our control therefore regular updates to this analysis are needed to maintain funding accuracy. Replacement cost is determined by our experience with similar projects, local vendor pricing and client historical records and should not be considered suitable for budgeting repair or replacement projects. Local contractor proposals must be obtained for this work. No liability is assumed as the result of changing market prices or inaccurate estimates or projections of remaining useful life of components.

Component replacement cost and interest rates constantly change. In order to maintain accuracy of your funding plan updates to this analysis should be conducted annually with a site visit every 2-3 years unless conditions warrant annual visits. Community Advisors, LLC shall not be required to participate in any legal action taken by or against our clients for any reason and shall also not be required to give testimony in depositions or in court. In all cases the liability of Community Advisors, LLC and its Principals, Employees, contractors and Vendors shall be limited to the consulting fee agreed upon for the production of this report. Client financial information is considered confidential and is not disclosed to third parties without your approval. We do use your name for our list of valued clients and when submitting proposals for new projects that request references or recent projects. That request may include size of property, number of units or major components. We also use photos from time to time of components as an example for educational and marketing efforts. Community Advisors and the analyst who prepared this study do not have any relationship that can be considered a conflict of interest. From time to time our Clients ask that we manage repair or replacement of components due to our experience in construction management. We do so with the understanding that full disclosure for both parties is completed.

#### **DEFINITIONS**

**Adjustment to Useful Life:** Typical useful life projections are used for each component. The adjustment is used to modify that life projection for earlier or later replacement. It only applies to the current replacement cycle.

**Cash Flow Method:** A method of determining reserve contributions that are "pooled" to fund replacement cost as needed without restricting funds to any one component.

**Component Method:** A funding method that fully funds each reserve component then sums those for the annual contribution.

**Current Funding Plan:** The funding plan currently used at the time of this analysis with updated component inventory and financial assumptions. This allows you to see how the current contribution level funds future component replacement.

**Effective Age:** Difference of useful and remaining useful life.

**Fully Funded Balance:** Represents the cost of used component life represented by the formula.

FFB = (Current Cost x Effective Age)/ Useful Life

**Interest Contribution:** The interest that should be earned on invested reserves.

**Percent Funded:** Ratio of reserve balance to fully funded balance.

**Remaining Life:** Number of years a component is projected to continue to function.

**Threshold Funding:** This plan maintains fund balance above a predetermined threshold dollar or percent funded amount.

**Useful Life:** The estimated useful life of an asset based upon industry standards, manufacturer specification, visual inspection, location, usage, association standards and prior history.